


GasWatch 3 Quick Reference Guide



START HERE



GasWatch 3 Quick Reference Guide

Turn On

Press & Hold

**POWER
MODE**

Past Due Bump/CAL

To Bump / CAL

**POWER
MODE**

Confirm & Use

AIR

CAL



BP - LMT

CAL



CAL - LMT

**Normal
Operation**

After brief
warm-up period

CO



0 ppm



10:42

Fresh Air


Press & Hold

AIR

Turn Off

Press & Hold

**POWER
MODE**



RKI Instruments, Inc. 33248 Central Ave, Union City, CA 94587

Phone (510) 441-5656 • (800) 754-5165 • www.rkiinstruments.com

200305/3000

