

GX-3R Pro Quick Reference Guide

Turn On

Press & Hold

**POWER
MODE**

Past Due Bump/CAL

To Bump / CAL

**POWER
MODE**

Confirm & Use

AIR

♥✓	7:49	📶	📶	🔋
CONFIRM TO USE USER MODE:MODE NO :AIR				
BUMP DATE PAST				
♥✓	7:49	📶	📶	🔋
CONFIRM TO USE USER MODE:MODE NO :AIR				
CAL DATE PAST				

**Normal
Operation**

After brief
warm-up period

♥✓	7:49	📶	📶	🔋	
CH4	%LEL	CO	ppm	H2S	ppm
	0		0		0.0
O2	%	CO2	vol%		
	20.9		0.00		

Fresh Air

Press & Hold


AIR

Turn Off

Press & Hold

**POWER
MODE**

GX-3R Pro Quick Reference Guide



Scan QR code for
GX-3R Pro Manual

RKI Instruments, Inc. 33248 Central Ave, Union City, CA 94587

Phone (510) 441-5656 • (800) 754-5165 • www.rkiinstruments.com

190422/250

